

SOUTH PRODUCTION NOTES

Jan 20, 2016
3-11 Shift Notes

BASF EMPLOYEES

54 Last Recordable
122 Last Lost time

SAFETY Notes: Check the walkways for ice and treat with icemelt. Need to remind operators that Styrene material on line #2 can't be washed down the drain.

Title V Notes: Trimer – Trimer is on ORP. Caustic pump is frozen and we are trying to get it working again. Keep an eye on the day tank. CTO – is still in manual, continue to stay above 25%SP or it will kick out.

Powder Room DC found with blowdowns off. Continuing blowing down. Need to evaluate replacing bags - **not completed yet.**

#1 MED / D 0713:

Not running until we get in more Versal – hopefully tomorrow. Use the acid and water numbers from the change order section of the MOD. **Be sure to feed the calciner in batch order.**

Do not increase the speed on the extruder to above 60 hz until IMC can correct the issue. Still need low level probe on miners installed, but is not needed for this product.

#1 RC / D 0713:

We need to start feeding after the 2nd impreg on the Pfaudler is complete and we get up to 250deg when drying the batch.

We need to top off SS#4 now that we are getting good material.

Make sure we feed the calciner in batch order.

#2 MED line / Styrene:

Continue making batches.

Need to remind operators that Styrene material can't be washed down the drain.

Installed auger #28. Auger #13 is on the floor behind #2 extruder and can be used next when we need a change out about 100,000# into the run.

#2 RC/ Styrene:

Continue feeding. We are checking to see if we can run to the F1, Justin to inform. Run to the CTO for now.

Need to remind operators that Styrene material can't be washed down the drain.

#3 MED line / AL 3945:

Hold off making batches, 30+ bags on the floor.

Need to remind operators to use their wet mix.

Try to keep extruder speed at 15Hz when we are running.

Please keep a close eye on the ammonia and nitric additions.

#3 RC / AL-3945:

Down for insulation installation.

#4 RC / D-0222 Cleaning:

Everything has been washed out of the calciner. Need to put back together.

There is one bag of the next size material that has been repacked and is staged by #4 RC. Hold this bag until we start up the next run.

#5 RC / Catoxid:

Feeding. Continue to monitor 5A after filter. Filter was changed out on day shift. The log sheet is in the 2nd floor MCC room bldg. 11 - needs to be filled out every 2 hrs.

#6 RC & Dryer / D-0761:

Calciner is coming up to temp. Start feeding material when ready.

West Pfaudler / D 4601:

Drying complete and solution made. Need to do 2nd impreg.

See special instructions from Andrea for the last 3 batches.

Save carbon lot: LA-15-6431: 1026 lb (1 bag) for the last batch (do not use on the next two batches). Geredco is scheduled to come in Jan 28th to do work on the Pro ring. We will need to be down at that point.

East Pfaudler/ D-0761:

Do not make any additional batches until RC#6 is running. Do not want material to sit around before feeding.

Engineer gave the go ahead to repack the material with the small extrusions.

6 Tank: Tank empty

Valve fixed. There was a screen and band clamp in the valve.

7 Tank: D-0226 Solution

Pumped out the solution in this tank. We have 2 totes worth on the 2nd floor to be used in the next run.

National Dryer / D-5206:

Schirmer finished soda blasting. Hold for next product.

PK Blender / Clean for Zr 0403:

We found that the lining is bad again. Goodman would like for us to fix the lining before continuing on with the pill mix due to being tight on the powders for this order. Gredco out to today and tomorrow to repair lining.

Dust collector can be blown down by switching the magnahelic gauge to 0 and then shutting off the blower when it starts to blow down.

DC gauge has been added to the Wonderware and has been moved over to near the weight tank. Gauge should be set at 3.5 and 4.25.

Abbe Blender / D 5206:

HF tote has been closed up and Abbe lid was remove and vessel cleaned out. Cover plates over open hole in floor have been reinstalled.

Tower 3 / AI 5645:

Done with testing do not need to staff

Tower 6 / AI 5645:

Done with testing do not need to staff.

Repacking in screening room:

North Screener / DPT-0101:

Room was cleaned on day shift.

South Screener / DPT-0101:

Room was cleaned on day shift.

#2662 (west) Pill Machine /

Back together and holding.

#2664 (east) Pill Machine /

Back together and holding.

TK #2 / Zr-0404:

The kiln is set up for the next run. We will light in a few weeks.

TK #4 / Cu 0203:

FYI- this product contains chrome and TK area is now a regulated area. Please wear your respirators in this area.

Milling V 2046: N/A

Harrop Kiln / AI 3920:

Hold off on lighting until after the Tower trainings. Plan to start 1/25/16.
Saggers have been switched out and are ready for next run.

Building 27 Belt Filter / Clean and set up for Cu-6081:

We will be down at least until the middle of next week waiting for raw materials.
WOW for leaking vacuum pump.

Priorities:

- 1) West Pfaudler/Trimer
- 2) CTO
- 3) #2 MED/RC
- 4) #5 RC
- 5) #1 MED/RC
- 6) #3 MED/RC
- 7) East Pfaudler/#6 RC (finish clean up)
- 8) #4 Tunnel Kiln changeover/Cu-0203 T
- 9) Zr-0403 T Tableting Line
- 10) #2 RC North